

HOUSING CONDITIONS

The data compiled in Table 11 reveals considerable information concerning available housing in the planning area. Using visual criteria, based on such exterior items as paint, weatherboarding, roof, foundation, and other structural conditions, the existing housing was inspected and classified during the recent land use survey. A grading system was established, giving a grade of standard, deteriorating or dilapidated to each house in the planning area. Mobile homes were not classified with the more permanent type dwellings although they were used in overall counts and for determining present population estimates. Table 11 also gives the residential density in dwelling unit per acre, based on the residential acreages for each study area as given in Table 10. Multi-family dwelling units are so few that they were not classed separately for these computations.

TABLE 11 Land Use Housing Survey Data

Study Area	DU's per Acre	Total Units	Per Cent	Stand-ard Units	Per Cent	Deteri-orated Units	Per Cent	Dilapi-dated Units	Per Cent	Mobile Homes*
CBD	--	1	100	--	--	1	100	--	--	--
1	2.3	134	100	80	59.7	47	35.1	7	5.2	3
2	2.5	536	100	363	67.8	155	28.9	18	3.3	37
Total Town	2.5	671	100	443	66.1	203	30.2	25	3.7	40
3	1.7	229	100	133	58.0	77	33.6	19	8.4	12
4	1.5	83	100	21	25.0	35	42.0	27	33.0	6
5	1.4	167	100	137	82.1	27	16.1	3	1.8	3
Total Fringe Area	1.5	479	100	291	61.0	139	28.9	49	10.1	21
Plan-ning Area	2.0	1,150	100	734	63.9	342	29.7	74	6.4	61

*Mobile homes are not included in the total units figures.

Source: Division of Community Planning. (Definitions of the classifications of standard, deteriorated and dilapidated are given on page 15.)